RELEASED under ATIA DIVULGUÉ en vertu LAI

National Capital Commission

Designated Substances Survey, Storage Barn, Harrington Lake, Gatineau Park, QC

Type of Document:
Final

Project Number:

Prepared By:
Reviewed By:

Date Submitted: June 7, 2019

RELEASED under ATIA National Capital Commission DIVULG Entraced Substances Survey LAI

June 7, 2019



Photograph No. 1

Exterior view of the storage barn. Notice parging walls above concrete foundation walls



Photograph No. 2


Notice the white texture coat, the paper layer and the grey soft plaster layer

RELEASED under ATIA National Capital Commission DIVULG Enter Bentin Vertu LAI

June 7, 2019



Photograph No. 3
View of the main barn room



Photograph No. 4
View suspected mould on paper on ceiling and underside of wood

RELEASED under ATIA National Capital Commission DIVULG Commission LAI

June 7, 2019



Photograph No. 5 View of the barn attic